

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problems Mailbox.**






FIG. 1A

10037277.041802



10037277.041802




FIG. 1D

10037277.041802




FIG. 1D'




FIG. 1E

10037277.041802





Fig. 2A

208T40" 422E00T




Fig. 2B

10037277.041802



Guilford Woven Loop

FIG. 3






Nonwoven PUB Loop Dots

FIG. 4

10037277, 041802





208740-222E001  
10037277-041802